



Job #2957193 - Fall Check Up

Untitled section 1 3zone system high efficiency furnace

System Amps	5.55	Heat Exchanger	Good
Motor Amps	3.53	Fuel Condition	Good
Inducer Amps	1.80	Thermostat	Good
Electrical Connections	Good	Gas Leaks Present	No
Igniter	Good	Gas Pressures	3.1
Flame Sensor	Good	Temperature Rise	25
Pressure Switch	Good	CO PPM	1
Burners	Good	OHMS	1

System Amps 5.55






Motor Amps 3.53




Inducer Amps 1.80




"Amp from the induce draft motor to make sure the induce draft motor is not over amping, and performing correctly"

Electrical Connections Good

Igniter Good



"Make sure that wires or not damage. To check the connection are tight, and that will not come a loose, which could cause problems in the future."



"Glow ignitor use for to ignite the flame when the gas valve open."


Flame Sensor **Good**



"Flame sensor senses that that a flame is present after ignition "

Pressure Switch **Good**

Burners **Good**



"Pressure switch is close when the induce draft blower motor comes on"

Thermostat **Good**



Gas Leaks Present **No**

